

Re: 602 HEI Distributor Notice September 22, 2021

GM has done a wonderful job of maintaining equal performance of the 602 engines despite numerous component changes due to all the supply shortages.

Somewhere mid 2021 there was a distributor change.

This is identified by the machine finish on the outside diameter of the distributor housing.

The new style distributor is shiny whereas the old is a flat finish. (See pictures.)

For the new style distributor, the vacuum lock-out bar had to be changed to accommodate the new style pick-up coil.

Also, the installation of the vacuum lock-out bar is different.

You will now install a bolt through the pickup coil into the bar.

The new style pickup coil has additional ID clearance in it, which is not desirable; however, the updated vacuum bar will stabilize the pickup and assist in alignment.

A complete instruction sheet will come with the kit.

We hope to do a video soon but, in the meantime, feel free to contact us with any questions.

All 3 components are available separately:

Mechanical bar,

Old-style vacuum lock-out bar, and

New style lock-out bar.

Additionally, we will have a discounted kit that will have both new and old-style vacuum lock-out bars

CII-40000 Mechanical Lock Bar.....	\$28
CII-40000V Old-Style Vacuum Lock Bar.....	\$22
CII-40000VN New Style Vacuum Lock Bar.....	\$22
CII-40000K Kit with Old-Style Vacuum Bar.....	\$40
CII-40000KN Kit with New Style Vacuum Bar.....	\$40
CII-40000KB Kit with Both New and Old-Style Vacuum Bars	\$47

